

A09 Alarm



The A09 alarm appears on MCZ pellet stoves when there is a fault in the flue gas temperature sensor. The sensor must be replaced.

This alarm often requires the intervention of a technician.