

Smoke ventilator fan failure - E08000.10 / E08000.08



The E08000.10 / E08000.08 alarm appears on Rika pellet stoves when the set rotation speed of the flue gas fan is not reached (number of rotations per minute).

Resolution

Acknowledge the error message and try to restart the stove

If this does not work, a check of the unit is necessary. It is possible that a foreign body is blocking the correct operation of the component.