

# Smoke ventilator fan failure - E08000.10 / E08000.08



The E08000.10 / E08000.08 alarm appears on Rika pellet stoves when the set rotation speed of the flue gas fan is not reached (number of rotations per minute).

## Resolution

Acknowledge the error message and try to restart the stove

If this does not work, a check of the unit is necessary. It is possible that a foreign body is blocking the correct operation of the component.