

# Ventilation flaps engine failure - E1000.04



The E1000.04 alarm appears on Rika pellet stoves when the ventilation dampers are not in the correct position.

## Resolution

1. Acknowledge the error message
2. Switch off the power supply, insert the socket wrench with handle and open the ventilation flaps fully and close them manually
3. Switch the power back on