Limiter / Overheated stove - E00020000.10 / E00020000.08



The E00020000.10 or E00020000.08 error code appears on Rika pellet stoves when there is excessive heat buildup inside the unit, often due to insufficient convection.

Solution

1. Let the stove cool down
2. Disconnect the power supply
3. Check that all convection and air vents are clear

Depending on the model: check the convection blower (Settings menu Multiair Fan, set to AUTO for both speed and power), then unlock and press the safety thermostat button on the back of the stove.