Limiter not connected or cable break - E00020000.02



The E00020000.02 alarm appears on Rika pellet stoves when the connection to the temperature limiter is interrupted (cable not connected or broken).

The stove can no longer operate. A technician must be called to inspect the wiring and the limiter.