Pressure Sensor Short Circuit - E2000.08



The E2000.08 alarm appears on Rika pellet stoves when a short circuit is detected in the pressure sensor (DAR system).

The stove can no longer operate. Contact your customer service representative to have the sensor and its wiring inspected.