Cable Break Pressure Sensor - E2000.02



The E2000.02 alarm appears on Rika pellet stoves when the connection to the pressure sensor is interrupted.

The stove can no longer operate. A technician must be called.