Pressure Sensor Timeout - E2000.01



The E2000.01 alarm appears on Rika pellet stoves when the required pressure differential has not been reached within the specified time.

Solution

1. Check that the firebox door and the cleaning flap are closed properly
2. Avoid disturbances in the room (such as a running range hood or closed windows that create negative pressure)
3. Check the chimney draft
4. Then clear the error message

If the error reappears, a technician must be called.