Uncalibrated Flame Temperature Sensor - E0100.10



The E0100.10 alarm appears on Rika pellet stoves when the calibration value of the flame temperature sensor is no longer valid.

Solution

1. Follow the on-screen instructions to restore the calibration

If the error reoccurs, a technician must be contacted.