Horizontal motor communication fault - E0800.10



The E0800.10 error code appears on Rika pellet stoves when communication between the horizontal motor and the main board is interrupted.

Solution

1. Let the stove cool down and unplug it from the power outlet
2. Disconnect the power supply for at least 10 seconds
3. Restore power
4. If the error reoccurs, a technician must be called