# Flue Damper Open - E0200.08



The E0200.08 error code appears on Rika pellet stoves when the flue damper is not in the heating position.

## Solution

1. Close the flue damper
2. Acknowledge the error message

If the error reoccurs, a technician must be called.