

Flame Temperature Sensor (Short-Circuit) - E0100.08



The E0100.08 alarm appears on Rika pellet stoves when a short circuit is detected in the flame temperature sensor.

The stove can no longer operate. Contact your customer service representative.