

# Pressure sensor is not calibrated - E2000.10



The E2000.10 alarm appears on Rika pellet stoves when the pressure sensor calibration value is not valid.

## Resolution

Carefully follow the instructions on the screen to restore the calibration value.