



The alarm A14 appears on the MCZ pellet stoves when there is a fault with the pressure transducer. The pressure transducer must be checked and, if necessary, replaced.

This alarm often requires the intervention of a technician.