

# A19 Alarm



The alarm A19 appears on the MCZ pellet stoves when there is a problem with the water temperature sensor. This sensor must be checked and if necessary replaced.

This alarm often requires the intervention of a technician.