

A23 Alarm

The alarm A23 appears on the MCZ pellet stoves when there is a problem with the room sensor. This sensor must be checked and replaced if necessary. This alarm can be triggered if the sensor is short-circuited.

This alarm often requires the intervention of a technician.