

Alarm AL 10



The alarm AL 10 - DRY SCREW appears on the KLOVER pellet stoves when the worm screw runs abnormally continuously.

This alarm often requires the intervention of a technician.